

**Flood Control Project Maintenance  
Levee Inspections**  
**LMA District Cover Sheet**  
**Spring 2008 Levee Inspection Results**

**Cache Creek**

---

|                                  | Spring<br>(March - May) | Summer **<br>(June - August) | Fall<br>(September - November) | Winter **<br>(December - February) |
|----------------------------------|-------------------------|------------------------------|--------------------------------|------------------------------------|
| * Overall LMA Rating (Fall Only) |                         |                              |                                |                                    |

\*\* Non-receipt of Summer or Winter Inspection Reports may effect overall annual rating.

\*

SPRING INSPECTIONS: Overall maintenance ratings are not determined for the spring inspection results. Individual maintenance deficiencies are rated using the same criteria in the spring and in the fall.

FALL INSPECTIONS: The overall maintenance rating shown above is based on operation and maintenance deficiencies identified within the attached unit inspection reports.

Comments

|  |
|--|
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |

**Flood Control Project Maintenance  
Levee Inspections  
Unit Cover Sheet  
Spring 2008 Levee Inspection Results  
Cache Creek**

| Waterway                |  | Bank | Unit Miles |
|-------------------------|--|------|------------|
| Unit No. 01 North Levee |  | Left | 11.81      |

|  | Spring<br>(March - May) | Summer<br>(June - August) | Fall<br>(September - November) | Winter<br>(December - February) |
|--|-------------------------|---------------------------|--------------------------------|---------------------------------|
| Date of Inspection                     | 3/26/2008               |                           |                                |                                 |
| DWR Inspector                          | John Williamson         |                           |                                |                                 |
| Accompanied By                         |                         |                           |                                |                                 |
| Unit Maintenance Rating<br>(Fall Only) |                         |                           |                                |                                 |

Check one:

☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

## Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.

|  |
|--|
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |

X

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2008**

**Cache Creek**

| Waterway                |            |       |               |               |            | Bank      | Unit Miles  | Inspection Date              |                              | Inspector       |       |
|-------------------------|------------|-------|---------------|---------------|------------|-----------|---|------------------------------|------------------------------|-----------------|-------|
| Unit No. 01 North Levee |            |       |               |               |            | Left      | 11.81   | 03/26/2008                   |                              | John Williamson |       |
| LMR Line                | Levee Mile |       | Category      | Item          | Location * | Rating ** | Action/Comment  | GPS Latitude/Longitude       |                              | Photo           | Issue |
|                         | Start      | End   |               |               |            |           |   | Start                        | End                          |                 |       |
| 1                       | 0.21       | 11.80 | Earthen Levee | Vegetation    | WS         | M         | Control annual grass and weeds on the levee slopes and easements. | 38.717012 °<br>-121.823102 ° | 38.698640 °<br>-121.674267 ° |                 | 2     |
| 2                       | 0.21       | 11.80 | Earthen Levee | Vegetation    | LS         | M         | Control annual grass and weeds on the levee slopes and easements. | 38.717012 °<br>-121.823100 ° | 38.698643 °<br>-121.674267 ° |                 | 1     |
| 3                       | 1.86       | 1.96  | Earthen Levee | Encroachments | LS         | PO        | Landscaping   | 38.729828 °<br>-121.806532 ° | 38.731143 °<br>-121.806255 ° |                 | 3     |
| 4                       | 1.91       | 1.91  | Earthen Levee | Encroachments | LS         | PO        | Buildings   | 38.730528 °<br>-121.806485 ° | 38.730528 °<br>-121.806485 ° |                 | 4     |
| 5                       | 1.92       | 1.94  | Earthen Levee | Encroachments | LS         | PO        | Equipment   | 38.730588 °<br>-121.806455 ° | 38.730942 °<br>-121.806333 ° |                 | 5     |
| 6                       | 1.96       | 1.99  | Earthen Levee | Encroachments | LS         | PO        | Landscaping   | 38.731198 °<br>-121.806230 ° | 38.731650 °<br>-121.806068 ° |                 | 7     |
| 7                       | 1.96       | 1.99  | Earthen Levee | Encroachments | WS         | PO        | Landscaping<br>Inspector Comments: cactus on waterside berm       | 38.731197 °<br>-121.806232 ° | 38.731655 °<br>-121.806068 ° |                 | 6     |
| 8                       | 1.98       | 1.98  | Earthen Levee | Encroachments | LS         | PO        | Buildings   | 38.731507 °<br>-121.806122 ° | 38.731507 °<br>-121.806122 ° |                 | 8     |
| 9                       | 2.01       | 2.01  | Earthen Levee | Encroachments | LS         | PO        | Buildings   | 38.731927 °<br>-121.805973 ° | 38.731927 °<br>-121.805973 ° |                 | 9     |
| 10                      | 2.03       | 2.03  | Earthen Levee | Encroachments | LS         | PO        | Buildings   | 38.732162 °<br>-121.805895 ° | 38.732162 °<br>-121.805895 ° |                 | 10    |
| 11                      | 2.04       | 2.04  | Earthen Levee | Encroachments | LS         | PO        | Buildings   | 38.732268 °<br>-121.805832 ° | 38.732268 °<br>-121.805832 ° |                 | 11    |
| 12                      | 2.05       | 2.05  | Earthen Levee | Encroachments | LS         | PO        | Buildings   | 38.732432 °<br>-121.805752 ° | 38.732432 °<br>-121.805752 ° |                 | 12    |
| 13                      | 2.06       | 2.06  | Earthen Levee | Encroachments | LS         | PO        | Buildings   | 38.732537 °<br>-121.805708 ° | 38.732537 °<br>-121.805708 ° |                 | 13    |
| 14                      | 2.10       | 2.11  | Earthen Levee | Encroachments | LS         | PO        | Landscaping   | 38.733117 °<br>-121.805367 ° | 38.733218 °<br>-121.805263 ° |                 | 14    |
| 15                      | 2.11       | 2.13  | Earthen Levee | Encroachments | LS         | CO        | Fences  | 38.733215 °<br>-121.805262 ° | 38.733350 °<br>-121.805082 ° |                 | 15    |
| 16                      | 2.15       | 2.15  | Earthen Levee | Encroachments | LS         | PO        | Buildings   | 38.733555 °<br>-121.804737 ° | 38.733555 °<br>-121.804737 ° |                 | 16    |
| 17                      | 2.60       | 2.60  | Earthen Levee | Encroachments | LS         | PO        | Buildings   | 38.732850 °<br>-121.796798 ° | 38.732850 °<br>-121.796798 ° |                 | 17    |
| 18                      | 2.62       | 2.62  | Earthen Levee | Encroachments | LS         | PO        | Equipment   | 38.732903 °<br>-121.796538 ° | 38.732903 °<br>-121.796538 ° |                 | 18    |
| 19                      | 2.65       | 2.70  | Earthen Levee | Encroachments | LS         | PO        | Equipment   | 38.733080 °<br>-121.796013 ° | 38.733492 °<br>-121.795293 ° |                 | 19    |

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2008**

**Cache Creek**

| Waterway                |            |      |               |               |            |           | Bank           | Unit Miles                   | Inspection Date              | Inspector          |       |
|-------------------------|------------|------|---------------|---------------|------------|-----------|----------------|------------------------------|------------------------------|--------------------|-------|
| Unit No. 01 North Levee |            |      |               |               |            |           | Left           | 11.81                        | 03/26/2008                   | John<br>Williamson |       |
| LMR Line                | Levee Mile |      | Category      | Item          | Location * | Rating ** | Action/Comment | GPS Latitude/Longitude       |                              | Photo              | Issue |
|                         | Start      | End  |               |               |            |           |                | Start                        | End                          |                    |       |
| 20                      | 2.66       | 2.66 | Earthen Levee | Encroachments | LS         | PO        | Buildings      | 38.733132 °<br>-121.795890 ° | 38.733132 °<br>-121.795890 ° |                    | 20    |
| 21                      | 2.71       | 2.71 | Earthen Levee | Encroachments | LS         | PO        | Firewood       | 38.733572 °<br>-121.795172 ° | 38.733572 °<br>-121.795172 ° |                    | 21    |
| 22                      | 2.85       | 2.85 | Earthen Levee | Encroachments | LS         | PO        | Debris         | 38.734200 °<br>-121.792633 ° | 38.734200 °<br>-121.792633 ° |                    | 22    |
| 23                      | 2.93       | 2.93 | Earthen Levee | Encroachments | LS         | M         | Prunings       | 38.734320 °<br>-121.791177 ° | 38.734320 °<br>-121.791177 ° |                    | 23    |
| 24                      | 3.00       | 3.00 | Earthen Levee | Encroachments | LS         | M         | Prunings       | 38.734347 °<br>-121.789998 ° | 38.734347 °<br>-121.789998 ° |                    | 24    |
| 25                      | 3.22       | 3.22 | Earthen Levee | Encroachments | LS         | M         | Prunings       | 38.735280 °<br>-121.786237 ° | 38.735280 °<br>-121.786237 ° |                    | 25    |
| 26                      | 3.61       | 3.61 | Earthen Levee | Encroachments | LS         | M         | Prunings       | 38.730702 °<br>-121.784850 ° | 38.730702 °<br>-121.784850 ° |                    | 26    |
| 27                      | 4.27       | 4.31 | Earthen Levee | Encroachments | LS         | PO        | Landscaping    | 38.727047 °<br>-121.774413 ° | 38.726890 °<br>-121.773770 ° |                    | 27    |
| 28                      | 5.23       | 5.23 | Earthen Levee | Encroachments | LS         | M         | Prunings       | 38.721535 °<br>-121.760698 ° | 38.721535 °<br>-121.760698 ° |                    | 28    |
| 29                      | 5.42       | 5.42 | Earthen Levee | Encroachments | LS         | M         | Prunings       | 38.724128 °<br>-121.760135 ° | 38.724128 °<br>-121.760135 ° |                    | 29    |
| 30                      | 5.73       | 5.73 | Earthen Levee | Encroachments | WS         | M         | Prunings       | 38.723708 °<br>-121.754950 ° | 38.723708 °<br>-121.754950 ° |                    | 30    |
| 31                      | 5.84       | 5.84 | Earthen Levee | Encroachments | LS         | M         | Prunings       | 38.724588 °<br>-121.753398 ° | 38.724588 °<br>-121.753398 ° |                    | 31    |
| 32                      | 5.95       | 5.95 | Earthen Levee | Encroachments | LS         | M         | Prunings       | 38.725712 °<br>-121.752043 ° | 38.725712 °<br>-121.752043 ° |                    | 32    |
| 33                      | 6.02       | 6.02 | Earthen Levee | Encroachments | LS         | M         | Prunings       | 38.726467 °<br>-121.751212 ° | 38.726467 °<br>-121.751212 ° |                    | 33    |
| 34                      | 6.11       | 6.11 | Earthen Levee | Encroachments | LS         | M         | Prunings       | 38.727393 °<br>-121.750102 ° | 38.727393 °<br>-121.750102 ° |                    | 34    |
| 35                      | 6.20       | 6.20 | Earthen Levee | Encroachments | LS         | M         | Prunings       | 38.727783 °<br>-121.748638 ° | 38.727783 °<br>-121.748638 ° |                    | 35    |
| 36                      | 6.25       | 6.25 | Earthen Levee | Encroachments | LS         | M         | Prunings       | 38.727893 °<br>-121.747707 ° | 38.727893 °<br>-121.747707 ° |                    | 36    |
| 37                      | 6.42       | 6.42 | Earthen Levee | Encroachments | LS         | M         | Prunings       | 38.728532 °<br>-121.744677 ° | 38.728532 °<br>-121.744677 ° |                    | 37    |
| 38                      | 6.69       | 6.69 | Earthen Levee | Encroachments | LS         | M         | Prunings       | 38.728858 °<br>-121.739770 ° | 38.728858 °<br>-121.739770 ° |                    | 38    |

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2008**

**Cache Creek**

| Waterway                |            |       |               |                       |            |           | Bank           | Unit Miles                   | Inspection Date              | Inspector       |       |
|-------------------------|------------|-------|---------------|-----------------------|------------|-----------|----------------|------------------------------|------------------------------|-----------------|-------|
| Unit No. 01 North Levee |            |       |               |                       |            |           | Left           | 11.81                        | 03/26/2008                   | John Williamson |       |
| LMR Line                | Levee Mile |       | Category      | Item                  | Location * | Rating ** | Action/Comment | GPS Latitude/Longitude       |                              | Photo           | Issue |
|                         | Start      | End   |               |                       |            |           |                | Start                        | End                          |                 |       |
| 39                      | 7.33       | 7.33  | Earthen Levee | Encroachments         | LS         | PO        | Buildings      | 38.727870 °<br>-121.728527 ° | 38.727870 °<br>-121.728527 ° |                 | 39    |
| 40                      | 7.33       | 7.38  | Earthen Levee | Encroachments         | LS         | PO        | Equipment      | 38.727878 °<br>-121.728553 ° | 38.728085 °<br>-121.727740 ° |                 | 40    |
| 41                      | 7.89       | 7.89  | Earthen Levee | Encroachments         | WS         | M         | Prunings       | 38.727710 °<br>-121.719325 ° | 38.727710 °<br>-121.719325 ° |                 | 41    |
| 42                      | 9.40       | 11.80 | Earthen Levee | Rip Rap<br>Revetments | WS         | A         |                | 38.720095 °<br>-121.697285 ° | 38.698637 °<br>-121.674267 ° |                 | 42    |

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected

**Flood Control Project Maintenance  
Levee Inspections  
Unit Cover Sheet  
Spring 2008 Levee Inspection Results  
Cache Creek**

| Waterway                |  | Bank  | Unit Miles |
|-------------------------|--|-------|------------|
| Unit No. 02 South Levee |  | Right | 11.41      |

|  | Spring<br>(March - May) | Summer<br>(June - August) | Fall<br>(September - November) | Winter<br>(December - February) |
|--|-------------------------|---------------------------|--------------------------------|---------------------------------|
| Date of Inspection                     | 3/25/2008               |                           |                                |                                 |
| DWR Inspector                          | John Williamson         |                           |                                |                                 |
| Accompanied By                         |                         |                           |                                |                                 |
| Unit Maintenance Rating<br>(Fall Only) |                         |                           |                                |                                 |

Check one:

☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.

☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

## Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.

|  |
|--|
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2008**

**Cache Creek**

| Waterway                |            |      |               |               |            | Bank      | Unit Miles  | Inspection Date              |                              | Inspector       |       |
|-------------------------|------------|------|---------------|---------------|------------|-----------|---|------------------------------|------------------------------|-----------------|-------|
| Unit No. 02 South Levee |            |      |               |               |            | Right     | 11.41   | 03/25/2008                   |                              | John Williamson |       |
| LMR Line                | Levee Mile |      | Category      | Item          | Location * | Rating ** | Action/Comment  | GPS Latitude/Longitude       |                              | Photo           | Issue |
|                         | Start      | End  |               |               |            |           |   | Start                        | End                          |                 |       |
| 1                       | 0.01       | 6.96 | Earthen Levee | Vegetation    | LS         | M         | Control annual grass and weeds on the levee slopes and easements. | 38.727407 °<br>-121.806102 ° | 38.712163 °<br>-121.717473 ° |                 | 1     |
| 2                       | 0.01       | 6.96 | Earthen Levee | Vegetation    | WS         | M         | Control annual grass and weeds on the levee slopes and easements. | 38.727407 °<br>-121.806103 ° | 38.712162 °<br>-121.717470 ° |                 | 2     |
| 3                       | 2.36       | 2.36 | Earthen Levee | Encroachments | LS         | M         | Debris  | 38.726222 °<br>-121.774877 ° | 38.726222 °<br>-121.774877 ° |                 | 3     |
| 4                       | 2.41       | 2.41 | Earthen Levee | Encroachments | LS         | M         | Equipment   | 38.725953 °<br>-121.773997 ° | 38.725953 °<br>-121.773997 ° |                 | 4     |
| 5                       | 2.57       | 2.57 | Earthen Levee | Vegetation    | LS         | A         | Elderberries are blocking visibility and flood fight capability.  | 38.724433 °<br>-121.771717 ° | 38.724433 °<br>-121.771717 ° |                 | 5     |
| 6                       | 2.60       | 2.60 | Earthen Levee | Vegetation    | LS         | A         | Elderberries are blocking visibility and flood fight capability.  | 38.724115 °<br>-121.771370 ° | 38.724115 °<br>-121.771370 ° |                 | 6     |
| 7                       | 3.48       | 3.57 | Earthen Levee | Encroachments | LS         | PO        | Landscaping   | 38.722228 °<br>-121.759663 ° | 38.723322 °<br>-121.759317 ° |                 | 7     |
| 8                       | 4.00       | 4.04 | Earthen Levee | Encroachments | LS         | PO        | Buildings   | 38.723922 °<br>-121.752593 ° | 38.724257 °<br>-121.752193 ° |                 | 8     |
| 9                       | 4.04       | 4.13 | Earthen Levee | Encroachments | LS         | PO        | Landscaping   | 38.724317 °<br>-121.752148 ° | 38.725242 °<br>-121.751075 ° |                 | 9     |
| 10                      | 4.41       | 4.44 | Earthen Levee | Encroachments | LS         | PO        | Landscaping   | 38.726875 °<br>-121.746422 ° | 38.727008 °<br>-121.745925 ° |                 | 10    |

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected

**Flood Control Project Maintenance  
Levee Inspections  
Unit Cover Sheet  
Spring 2008 Levee Inspection Results  
Cache Creek**

| Waterway  |                         |                           | Bank                           | Unit Miles                      |
|---|-------------------------|---------------------------|--------------------------------|---------------------------------|
| Unit No. 04 East Training Levee of Cache Creek Settling Basin |                         |                           | Left                           | 2.61                            |
|   | Spring<br>(March - May) | Summer<br>(June - August) | Fall<br>(September - November) | Winter<br>(December - February) |
| Date of Inspection  | 3/25/2008               |                           |                                |                                 |
| DWR Inspector   | John Williamson         |                           |                                |                                 |
| Accompanied By  |                         |                           |                                |                                 |
| Unit Maintenance Rating<br>(Fall Only)                        |                         |                           |                                |                                 |

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

## Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.

|  |
|--|
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |

X

Signature of LMA Representative

Date



**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2008**

**Cache Creek**

| Waterway  | Bank | Unit Miles | Inspection Date | Inspector       |
|---|------|------------|-----------------|-----------------|
| Unit No. 04 East Training Levee of Cache Creek Settling Basin | Left | 2.61       | 03/25/2008      | John Williamson |

| LMR Line | Levee Mile |      | Category      | Item       | Location * | Rating ** | Action/Comment  | GPS Latitude/Longitude       |                              | Photo | Issue |
|----------|------------|------|---------------|------------|------------|-----------|---|------------------------------|------------------------------|-------|-------|
|          | Start      | End  |               |            |            |           |   | Start                        | End                          |       |       |
| 1        | 0.03       | 2.28 | Earthen Levee | Vegetation | WS         | M         | Control annual grass and weeds on the levee slopes and easements. | 38.727120 °<br>-121.718015 ° | 38.695365 °<br>-121.715942 ° |       | 2     |
| 2        | 0.03       | 2.28 | Earthen Levee | Vegetation | LS         | M         | Control annual grass and weeds on the levee slopes and easements. | 38.727120 °<br>-121.718015 ° | 38.695367 °<br>-121.715940 ° |       | 1     |

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected

**Flood Control Project Maintenance  
Levee Inspections  
Unit Cover Sheet  
Spring 2008 Levee Inspection Results  
Cache Creek**

| Waterway   |                         |                           | Bank                           | Unit Miles                      |
|--|-------------------------|---------------------------|--------------------------------|---------------------------------|
| Unit No. 05 Cache Creek Settling Basin Extension Levee |                         |                           |                                | 3.17                            |
|  | Spring<br>(March - May) | Summer<br>(June - August) | Fall<br>(September - November) | Winter<br>(December - February) |
| Date of Inspection                                     | 3/25/2008               |                           |                                |                                 |
| DWR Inspector  | John Williamson         |                           |                                |                                 |
| Accompanied By   |                         |                           |                                |                                 |
| Unit Maintenance Rating<br>(Fall Only)                 |                         |                           |                                |                                 |

Check one:

- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. We have found no changes in flood project conditions other than the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the enclosed report.
- ☐ During the current winter (or summer) inspection period, my staff or I have inspected the levee and associated flood project components identified in the attached Levee Inspection Report by Mile. In addition to the results of our normal maintenance and the corrections we have made to maintenance deficiencies identified in the report, we have found the following changes in flood project conditions.

(In the comment section below or on additional sheet(s), identify change of condition by: Start to End Levee Mile or GPS coordinates, location (Land Side, Water Side, or Crown), Item identification, and description of the current condition).

## Comments

One of the boxes above is to be checked by the Local Maintaining Agency (LMA). If the second box is checked, additional information must also be submitted. This Unit Cover Sheet should be signed and dated by the LMA Representative and returned to DWR with any additional sheets by September 30 (Summer Inspection) or March 31 (Winter Inspection). Please retain a copy for your records. Please mail all of this information to :

DWR Summer/Winter Inspection Reports  
3310 El Camino Avenue, Room LL-30  
Sacramento, CA 95821-9000.

|  |
|--|
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |
|  |

**X**

Signature of LMA Representative

Date

**Flood Control Project Maintenance  
Levee Inspections**

**Levee Inspection Report By Mile - Spring 2008**

**Cache Creek**

| Waterway   | Bank | Unit Miles | Inspection Date | Inspector       |
|--|------|------------|-----------------|-----------------|
| Unit No. 05 Cache Creek Settling Basin Extension Levee |      | 3.17       | 03/25/2008      | John Williamson |

| LMR Line | Levee Mile |       | Category      | Item               | Location * | Rating ** | Action/Comment  | GPS Latitude/Longitude       |                              | Photo | Issue |
|----------|------------|-------|---------------|--------------------|------------|-----------|---|------------------------------|------------------------------|-------|-------|
|          | Start      | End   |               |                    |            |           |   | Start                        | End                          |       |       |
| 1        | 6.96       | 11.41 | Earthen Levee | Vegetation         | LS         | M         | Control annual grass and weeds on the levee slopes and easements. | 38.712195 °<br>-121.717505 ° | 38.677910 °<br>-121.673270 ° |       | 1     |
| 2        | 6.96       | 11.41 | Earthen Levee | Vegetation         | WS         | M         | Control annual grass and weeds on the levee slopes and easements. | 38.712202 °<br>-121.717502 ° | 38.677908 °<br>-121.673270 ° |       | 2     |
| 3        | 7.98       | 8.83  | Earthen Levee | Rip Rap Revetments | WS         | A         |   | 38.697518 °<br>-121.718305 ° | 38.685918 °<br>-121.715040 ° |       | 3     |
| 4        | 9.25       | 9.36  | Earthen Levee | Rip Rap Revetments | WS         | A         |   | 38.680418 °<br>-121.711570 ° | 38.678927 °<br>-121.710632 ° |       | 4     |
| 5        | 9.47       | 11.41 | Earthen Levee | Rip Rap Revetments | WS         | A         |   | 38.678128 °<br>-121.709277 ° | 38.677897 °<br>-121.673270 ° |       | 5     |

**\* Location**

LS : Land Side  
WS : Water Side  
CR : Crown

**\*\* Rating**

A : Acceptable  
M : Minimally Acceptable  
U : Unacceptable  
PO : Partially Obstructing  
CO : Completely Obstructing  
N : Not Inspected